



## **E.SYBOX VERSION SW 4.12**

Improvements introduced with the firmware  
version SW 4.12



## 1) Improved wireless connectivity:

- Enhanced stability between e.sybox and e.sylink.
- Ability to connect with e.sylink (Input & Output device) enabling remote inputs and outputs for alarm and status (BMS functions).
- Implementation of the KIWA function, to control the system through the minimum pressure switch;



## 2) Firmware update:

- e.sybox with SW 4.12 can upgrade other e.sybox with previous versions installed.
- It imposes the alignment of the FW version of all e.sybox in communication
- Keeps the user settings and the historical information even after upgrading from previous versions.

### Communication compatibility between different SW versions

Version	1.11	2.7	3.11	4.XX
1.11	OK	NO	NO	OK
2.7		OK	NO	OK
3.11			OK	OK
4.XX				OK



## 3) New languages:

Increased usability enabled by the inclusion of two new languages: Czech and Polish.

## 4) Solved false alarms E18-19 and E20-21:

Revised the intervention thresholds of certain protections that create false errors.

Added Pop up displaying the type of error (E18-19, locked rotor or E20-21, dry running), the message "Please wait while letting powered" and the countdown for recovery.




## Identification Sw 4.12:

- Packaging label:



- Display menu:





WATER • TECHNOLOGY

[www.dabpumps.com](http://www.dabpumps.com)